

AUDI P3211: EXHAUST-HEATER RETURN CONNECTION (BANK 1 - SENSOR 1)

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Audi P3211 Code Mean?

Condition for setting the DTC:

Exhaust temp. -300-700° C. Sensor voltage -3.7-4.84 V. Dew point - Exceeded

What Are The Potential Causes Of The Audi P3211 Code?

Below are some potential causes of this DTC:

- Check activation of Recirculation Pump Relay
- Oxygen sensor (before catalytic converter) is faulty
- Oxygen sensor (behind catalytic converter) is faulty
- Oxygen sensor heater (before catalytic converter) is faulty
- Oxygen sensor heater (behind catalytic converter) is faulty

Reference Sources

[Audi P3211](#), DTCDECODE.