

BMW P1012: VALVETRONIC (VVT) REFERENCE SENSOR SOLENOID LOSS (BANK 1)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Does The BMW P1012 Code Mean?

After 3ms and the DME and VVT are active, it is detected that the sensor is missing a magnet.

What Are The Potential Causes Of The BMW P1012 Code?

Defective sensor.

Reference Sources

[BMW P1012](#), DTCDECODE.