BMW P1012: VALVETRONIC (VVT) REFERENCE SENSOR SOLENOID LOSS (BANK 1) OVERVIEW

Severity

DIY Difficulty Level

Repair Cost \$100-\$200

Can I Still Drive? Yes

What Does The BMW P1012 Code Mean?

After 3ms and the DME and VVT are active, it is detected that the sensor is missing a magnet.

What Are The Potential Causes Of The BMW P1012 Code?

Defective sensor.

Reference Sources

BMW P1012, DTCDECODE.

