BMW P1041: VALVETRONIC (VVT) ACTUATOR CONTROL MODULE EEPROM ERROR (BANK 1)

OVERVIEW

Severity : High

DIY Difficulty Level : Advanced

Repair Cost : \$300-\$450

Can I Still Drive? : Yes

What Does The BMW P1041 Code Mean?

Ignition on for 50ms, the DME detected a control module malfunction (software). To achieve optimal anti-theft protection for the vehicle, an anti-theft immobilizer is installed.

What Are The Potential Causes Of The BMW P1041 Code?

- Engine Control Module (DME) has failed
- Voltage supply for Engine Control Module (DME) has shorted

Reference Sources

BMW P1041, DTCDECODE.