BMW P1050: VALVETRONIC (VVT) CONTROL CIRCUIT (BANK 1) OVERVIEW Severity: Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$75-\$200

Can I Still Drive? : Yes (Short-term only)

What Does The BMW P1050 Code Mean?

This code indicates that key on for 3ms, and the DME detected that the Control Circuit triggered a general fault.

What Are The Potential Causes Of The BMW P1050 Code?

This fault is usually overwritten by three other faults before the user recognizes it.

Reference Sources

ENGINE PERFORMANCE Self Diagnosis for P1050 - 2011 BMW 535xi, pages 541-543.

