BMW P1052: VALVETRONIC (VVT) CONTROL CIRCUIT LOW INPUT (BANK 1)

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$75-\$200

Can I Still Drive? : Yes

What Does The BMW P1052 Code Mean?

Key on for 3ms, and the DME detected a short to ground. Check wiring harness or otherwise replace the servo.

What Are The Potential Causes Of The BMW P1052 Code?

- Short to ground in Kb-B
- KS ground in Kb-B
- KS motor to ground
- KS motor winding

Reference Sources

BMW P1052, DTCDECODE.

