

BMW P1055: VALVETRONIC (VVT) SUPPLY VOLTAGE CONTROL MOTOR HIGH INPUT (BANK 1)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The BMW P1055 Code Mean?

Key on for 200ms, the DME detected that the supply voltage was too high (more than 17 volts). This is a jump-start detection that throws a fault if there is 24 volts of power for longer than 21 seconds.

What Are The Potential Causes Of The BMW P1055 Code?

Check electrical system for faults.

Reference Sources

[BMW P1055](#), DTCDECODE.