BMW P1058: VALVETRONIC (VVT) SUPPLY VOLTAGE CONTROL MOTOR HIGH INPUT (BANK 2)

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$75-\$200

Can I Still Drive? : Yes

What Does The BMW P1058 Code Mean?

Key on for 200ms, the DME detected that the supply voltage was too high (more than 17 volts). This is a jump-start detection that throws a fault if there is 24 volts of power for longer than 21 seconds.

What Are The Potential Causes Of The BMW P1058 Code?

Check electrical system for faults.

Reference Sources

BMW P1058, DTCDECODE.

