## BMW P1059: VALVETRONIC (VVT) SUPPLY VOLTAGE CONTROL MOTOR LOW INPUT (BANK 2)

**OVERVIEW** 

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$75-\$200

Can I Still Drive? : Yes

## What Does The BMW P1059 Code Mean?

Key on for 200ms, the DME detected that the supply voltage was too low (less than 5 volts).

## What Are The Potential Causes Of The BMW P1059 Code?

- VVT fuse is faulty
- Defective load reduction relay
- Plug/Kb-B open circuit in power supply circuit
- Plug/Kb-B open circuit in relay supply circuit

## **Reference Sources**

BMW P1059, DTCDECODE.

