## BMW P1060: VALVETRONIC (VVT) SUPPLY VOLTAGE CONTROL MOTOR ELECTRICAL (BANK 2)

**OVERVIEW** 

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$75-\$200

**Can I Still Drive?** : Yes (Short-term only)

## What Does The BMW P1060 Code Mean?

This code indicates that key on for 50ms, the DME detected that the supply voltage was irregular.

## What Are The Potential Causes Of The BMW P1060 Code?

Short to ground at power input or defective ECU (capacitor preload).

## **Reference Sources**

BMW P1060, DTCDECODE.

