

BMW P1063: VALVETRONIC (VVT) LIMP HOME REQUEST AIR MASS PLAUSIBILITY (BANK 1)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The BMW P1063 Code Mean?

This code indicates the condition that:

After 4000ms the eccentric overload angle detected a fault with the mass airflow plausibility. Other VVT fault issues maximum stroke command but the position is not reached.

How Can You Fix The BMW P1063 Code?

Resolve the primary fault.

Reference Sources

[BMW P1063](#), DTCDECODE.