## BMW P1067: VALVETRONIC (VVT) REFERENCE SENSOR SOLENOID LOSS (BANK 2)

**OVERVIEW** 

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$100-\$200

Can I Still Drive? : Yes

## What Does The BMW P1067 Code Mean?

After 3ms and the DME and VVT are active, it is detected that the sensor is missing a magnet.

## What Are The Potential Causes Of The BMW P1067 Code?

Defective sensor.

## **Reference Sources**

BMW P1067, DTCDECODE.

