## BMW P1070: VALVETRONIC (VVT) REFERENCE SENSOR GRADIENT ERROR (BANK 2)

**OVERVIEW** 

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$100-\$200

Can I Still Drive? : Yes

## What Does The BMW P1070 Code Mean?

After 9ms and the DME and VVT are active, it is detected that the sensor has a gradient violation/identity, causing a reading of implausible sensor data. The plug is defective on the sensor or there is an open circuit.

## **How Can You Fix The BMW P1070 Code?**

Replace sensor

## **Reference Sources**

BMW P1070, DTCDECODE.

