WATCHDOG OR TEMPERATURE SENSOR ERROR (BANK 2)		
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$150
Can I Still Drive?	:	Yes (Short-term only)

## What Does The BMW P1072 Code Mean?

This code indicates that key on for 10ms, and the DME detected an internal fault relating to an internal temperature sensor. Ignore single isolated appearances and only respond to repeated occurrences by replacing the VVT-SG.

## What Are The Potential Causes Of The BMW P1072 Code?

Below are some potential causes of this DTC:

- Battery terminal corrosion, or loose battery connection
- Connection to the DME interrupted, or the circuit has been opened
- Reprogramming error has occurred

## **Reference Sources**

BMW P1072, DTCDECODE.

