

## What Does The BMW P1101 Code Mean?

Engine running, with the system voltage more than 11.0v, and the temperature must be at least 185-degrees (F) and all electrical equipment (A/C, lights, etc) must be off. The DME has detected that the MAF signal was out of a calculated range.

## What Are The Potential Causes Of The BMW P1101 Code?

- Mass air flow (MAF) sensor has failed or is damaged
- Signal and ground wires of Mass Air Flow (MAF) sensor has short circuited

## **Reference Sources**

BMW Fault Codes (DTCs), page 7.

