

## BMW P1199: DIFFERENTIAL PRESSURE SENSOR INTAKE MANIFOLD PRESSURE PLAUSIBILITY (BANK 1)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes

### What Does The BMW P1199 Code Mean?

Engine started, battery voltage must be at least 11v, and the differential pressure sensor signal is malfunction or is not present. The closed loop control of the differential pressure in the intake manifold is suspended and replaced.

### What Are The Potential Causes Of The BMW P1199 Code?

- Sensor's voltage supply on Terminal 87
- Sensor's ground connection faulty
- Signal wire to DME faulty
- Replace sensor

### Reference Sources

[BMW P1199](#), DTCDECODE.