

BMW P1473: EVAP EMISSION CONTROL LEAK DETECTION PUMP CIRCUIT OPEN

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$350-\$550
Can I Still Drive?	:	Yes

What Does The BMW P1473 Code Mean?

Key on, KOEO Self-Test enabled, and the DME detected an unexpected voltage condition on the EVAP emission control leak detection pump circuit.

What Are The Potential Causes Of The BMW P1473 Code?

- Leak Detection Pump has failed
- EVAP canister system has an improper or broken seal
- Evaporative Emission (EVAP) canister purge regulator valve 1 is faulty
- Hoses between the fuel pump and the EVAP canister are faulty
- Fuel filler cap is loose

Reference Sources

[BMW P1473](#), DTCDECODE.