

BMW P1515: ENGINE OFF TIMER PLAUSIBILITY

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The BMW P1515 Code Mean?

The DME detected an implausible instrument cluster and/or power module signal. CAN signal failure while the DME was operating at a range between 6 and 16 volts. CAN Bus lost communications. The system time (time pulse) is implausible relative to the DME.

What Are The Potential Causes Of The BMW P1515 Code?

- Check the CAN bus
- Check instrument cluster/power module/Can Signal if no other CAN faults are detected

Reference Sources

[BMW P1515](#), DTCDECODE.