TOO HIGH			
	(OVERVIEW	
Severity	:		High
DIY Difficulty Level	:	Intermediate	
Repair Cost	:	\$100-\$300	
Can I Still Drive?	:	No	

What Does The BMW P1518 Code Mean?

The DME detected an electrical malfunction on the main relay circuit.

What Are The Potential Causes Of The BMW P1518 Code?

Possible failure of wheel speed sensor on drive axle.

Reference Sources

BMW P1518, DTCDECODE.

