

## BMW P1519: ENGINE OIL QUALITY SENSOR TEMPERATURE MEASUREMENT

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>High</div></div>         |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$100-\$300                        |
| Can I Still Drive?   | : | Yes                                |

### What Does The BMW P1519 Code Mean?

The oil temperature difference of greater than 100 degrees within one second. The ignition must be on. The DME detected an error in the Engine Oil Temperature sensor.

### What Are The Potential Causes Of The BMW P1519 Code?

Replace the oil temperature sensor.

### Reference Sources

[BMW Fault Codes \(DTCs\)](#), page 5.