

What Does The BMW P1521 Code Mean?

Key on or engine running; and the DME detected the intake manifold control signal for was outside of its expected calibrated range.

What Are The Potential Causes Of The BMW P1521 Code?

Below are some potential causes of this DTC:

- Camshaft control circuit is open or shorted to ground
- Camshaft sensor is damaged or the DME has failed
- Camshaft out of adjustment

Reference Sources

BMW P1521, DTCDECODE.

