

BMW P1522: INTAKE CAMSHAFT CONTROL (BANK 2) MALFUNCTION

OVERVIEW

Severity	:		High
DIY Difficulty Level	:		Intermediate
Repair Cost	:	\$200-\$400	
Can I Still Drive?	:	No	

What Does The BMW P1522 Code Mean?

Key on or engine running; and the DME detected the intake manifold control signal for was outside of its expected calibrated range.

What Are The Potential Causes Of The BMW P1522 Code?

- Camshaft control circuit is open or shorted to ground
- Camshaft sensor is damaged or the DME has failed
- Camshaft out of adjustment

Reference Sources

[BMW Fault Codes \(DTCs\)](#), page 5.