

BMW P1536: DIFFERENTIATED INTAKE MANIFOLD CONTROLLER MONITORING, CONTROL DEVIATION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div>Advanced</div>
Repair Cost	:	\$400-\$800
Can I Still Drive?	:	Yes

What Does The BMW P1536 Code Mean?

This fault stems from the 4.8L-N62 equipped with an infinitely adjustable control of induction system.

What Are The Potential Causes Of The BMW P1536 Code?

Faulty controller

Reference Sources

[BMW P1536](#), DTCDECODE.