

BMW P1537: DIFFERENTIATED INTAKE MANIFOLD POTENTIOMETER VOLTAGE IN LOWER DIAGNOSIS RANGE

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$400-\$800
Can I Still Drive?	:	Yes (Short-term only)

What Does The BMW P1537 Code Mean?

This fault stems from the 4.8L-N62 equipped with an infinitely adjustable control of induction system.

What Are The Potential Causes Of The BMW P1537 Code?

Faulty potentiometer

Reference Sources

[BMW P1537](#), DTCDECODE.