

## BMW P1551: ENGINE OFF TIMER TIMEOUT

### OVERVIEW

<b>Severity</b>	:		High
<b>DIY Difficulty Level</b>	:		Intermediate
<b>Repair Cost</b>	:	\$100-\$1500	
<b>Can I Still Drive?</b>	:	No	

### What Does The BMW P1551 Code Mean?

The DME detected a CAN signal failure while the DME was operating at a range between 6 and 16 volts. CAN Bus lost communications.

### What Are The Potential Causes Of The BMW P1551 Code?

- Check the CAN bus
- Check instrument cluster/power module/Can Signal

### Reference Sources

[BMW P1551](#), DTCDECODE.