

BMW P1734: PRESSURE CONTROL VALVE 2 ELECTRICAL

OVERVIEW

Severity	:		High
DIY Difficulty Level	:		Intermediate
Repair Cost	:	\$75-\$450	
Can I Still Drive?	:	Yes	(Short-term only)

What Does The BMW P1734 Code Mean?

The pressure control valve is not receiving nor sending a signal.

What Are The Potential Causes Of The BMW P1734 Code?

Below are some potential causes of this DTC:

- Pressure control solenoid circuit is shorting to ground
- Pressure control solenoid circuit is open
- Valve has failed
- TCM has failed

Reference Sources

[BMW P1734](#), DTCDECODE.