

## BMW P1743: PRESSURE REGULATOR VALVE 5 UPPER THRESHOLD

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div></div></div> High        |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$75-\$450                         |
| Can I Still Drive?   | : | <b>Yes</b> (Short-term only)       |

### What Does The BMW P1743 Code Mean?

The signal to/from the pressure regulator valve has been interrupted.

### What Are The Potential Causes Of The BMW P1743 Code?

Below are some potential causes of this DTC:

- Pressure control solenoid circuit is shorting to ground
- Pressure control solenoid circuit is open
- Valve has failed
- TCM has failed

### Reference Sources

[BMW P1743](#), DTCDECODE.