

## BMW P1750: SHIFT SOLENOID POWER SUPPLY MALFUNCTION

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>High</div></div>         |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$200-\$500                        |
| Can I Still Drive?   | : | No                                 |

### What Does The BMW P1750 Code Mean?

The shift solenoid valve is not receiving a proper power supply after 300ms of operation.

### What Are The Potential Causes Of The BMW P1750 Code?

Below are some potential causes of this DTC:

- Pressure control solenoid circuit is shorting to ground
- Pressure control solenoid circuit is open
- Valve has failed
- TCM has failed

### Reference Sources

[BMW P1750](#), DTCDECODE.