

BMW P1753: PRESSURE REGULATOR VALVE 4 UPPER THRESHOLD

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$450
Can I Still Drive?	:	Yes

What Does The BMW P1753 Code Mean?

The signal to/from the pressure regulator valve has been interrupted.

What Are The Potential Causes Of The BMW P1753 Code?

- Pressure control solenoid circuit is shorting to ground
- Pressure control solenoid circuit is open
- Valve has failed
- TCM has failed

Reference Sources

[BMW P1753](#), DTCDECODE.