DIVIVV I 1005.	P1863: 4-3 SHIFT RANGE MONITORING		
		OVERVIEW	
Severity	:	Medium	
DIY Difficulty Level	:	Intermediate	
Repair Cost	:	\$200-\$500	
Can I Still Drive?	:	Yes	

## What Does The BMW P1863 Code Mean?

Engine running and vehicle driven, the DME detected a mechanical malfunction within the transmission. The output speed is greater than 300rpm, the transmission oil temperature is greater than 0 degrees Celsius.

## What Are The Potential Causes Of The BMW P1863 Code?

- Solenoid valves in valve body are faulty
- Solenoid circuit is shorting to ground
- Solenoid circuit is open
- TCM has failed or wiring is shorting

## **Reference Sources**

BMW P1863, DTCDECODE.

