

BMW P3225: GENERATOR COMMUNICATION ERROR

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$380-\$1100
Can I Still Drive?	:	No

What Does The BMW P3225 Code Mean?

The engine is running for at least 25 seconds, and there is no communication faults at the BSD Interface.

What Are The Potential Causes Of The BMW P3225 Code?

Below are some potential causes of this DTC:

- Wires have short circuited to each other
- ECU has failed
- Generator failure

Reference Sources

[BMW P3225](#), DTCDECODE.