

## CADILLAC B1514: INSTRUMENT PANEL CLUSTER VOLTAGE HIGH INPUT

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$600-\$900
Can I Still Drive?	:	No

### What Does The Cadillac B1514 Code Mean?

DTC P1327 not set, engine started, engine speed over 1,500 rpm, and the PCM received a “high voltage” message on the Class 2 data line from the Instrument panel cluster (IPC). The IPC detected the system voltage was more than 16.0v for 30 seconds.

### What Are The Potential Causes Of The Cadillac B1514 Code?

- Check the operation of the Charging system (Generator)
- The charge indicator and driver warning message are set in the driver information center (DIC)
- IPC is damaged or has failed

### Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).