CADILLAC C1277: REQUESTED TORQUE SIGNAL CIRCUIT MALFUNCTION OVERVIEW Severity: High DIY Difficulty Level: Advanced Repair Cost: \$300-\$1000 Can I Still Drive?: Yes

What Are The Potential Causes Of The Cadillac C1277 Code?

- An open in the requested torque circuit
- An short to ground or voltage in the requested torque circuit
- A wiring problem, terminal corrosion, or poor connection in the requested torque circuit

Reference Sources

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

