

CADILLAC C128F: ABS REGENERATIVE AXLE PRESSURE SENSOR RAW OFFSET ERROR

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$800
Can I Still Drive?	:	Yes

What Does The Cadillac C128F Code Mean?

Ignition ON. Ignition voltage is greater than 10 volts.

What Are The Potential Causes Of The Cadillac C128F Code?

- Internal sensor failure is detected.

Reference Sources

[Cadillac C128F](#), DTCDECODE.