

CADILLAC P1108: BARO TO MAP SENSOR COMPARISON TOO HIGH

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac P1108 Code Mean?

Conditions for setting the DTC:

- DTCs [P0107](#), [P0108](#), [P0122](#), [P0123](#), not set.
- Throttle position at idle , calculated by the PCM.
- TP sensor 18 degrees or less.
- Engine speed 400 RPM or greater.
- Barometric pressure 75 kPa or gr.

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).