

CADILLAC P1114: ECT SENSOR CIRCUIT INTERMITTENT LOW INPUT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac P1114 Code Mean?

DTC [P0112](#), [P0113](#), [P1111](#) and [P1112](#) not set, engine started, IAT sensor less than 158°F, engine runtime over 10 seconds, and the PCM detected an intermittent low voltage condition on the ECT sensor signal circuit (Scan Tool reads over 300°F) for 10 seconds.

What Are The Potential Causes Of The Cadillac P1114 Code?

- ECT sensor signal circuit shorted to ground (intermittent fault)
- ECT sensor has failed (possible intermittent shorted condition)
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).