

CADILLAC P1260: FUEL PUMP SPEED RELAY CONTROL CIRCUIT MALFUNCTIONS

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$60-\$150
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Cadillac P1260 Code?

- FP speed relay control circuit is open or shorted to ground
- FP speed relay control circuit is shorted to system power
- FP speed relay power circuit is open (test the FP relay fuse)
- FP speed relay is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).