

CADILLAC P1320: ICM 4X REFERENCE CIRCUIT NO PULSES (INTERMITTENT)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$550
Can I Still Drive?	:	No

What Does The Cadillac P1320 Code Mean?

DTC [P0232](#) and [P1376](#) not set, engine started, engine speed over 568 rpm, and the PCM detected an interruption of the 4X Fuel Control pulses for 400 ms during the CCM test.

What Are The Potential Causes Of The Cadillac P1320 Code?

- Ignition control (4X) circuit is open, shorted to ground or to B+
- Ignition module power circuit is open (test power from DS fuse)
- Ignition module is damaged or has failed
- PCM has failed
- TSB 71-65-69 contains a repair procedure for this code

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).