

CADILLAC P1350: IGNITION CONTROL (IC) CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$550
Can I Still Drive?	:	No

What Does The Cadillac P1350 Code Mean?

DTC [P0322](#) and [P1376](#) not set, engine cranking with at least one 4X REF pulse detected, and the PCM detected Ignition Control (IC) pulses with the engine cranking, or it detected at least one 4X REF pulse while it did not detect any IC pulses with the engine.

What Are The Potential Causes Of The Cadillac P1350 Code?

- Bypass circuit or the IC Signal circuit is open, shorted to ground or shorted to power
- IC module has failed

How Can You Fix The Cadillac P1350 Code?

TSB 71-65-69 contains a repair procedure for this code

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).