

CADILLAC P1351: ICM IGNITION CONTROL CIRCUIT HIGH INPUT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div>Advanced</div>
Repair Cost	:	\$50-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac P1351 Code Mean?

Engine started; and the PCM detected an intermittent high voltage condition (over 4.60v) on the IC circuit during the CCM test.

What Are The Potential Causes Of The Cadillac P1351 Code?

Below are some potential causes of this DTC:

- Bypass circuit is open, shorted to ground or shorted to power
- IC signal circuit is open, shorted to ground or shorted to power
- IC module has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).