

CADILLAC P1374: IC MODULE 3X REFERENCE CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$50-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Cadillac P1374 Code?

- IC 3X signal wire is routed to close to the Generator, spark plug wires or any other possible cause of EMI/RFI interference
- IC 3X signal circuit is open, shorted to ground or shorted to B+
- IC module is damaged or has failed
- PCM has failed
- TSB 99-06-04-45 contains a repair procedure for this code

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).