

CADILLAC P1441: EVAP SYSTEM FLOW DURING NON-PURGE

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Cadillac P1441 Code?

- An improperly installed or damaged EVAP canister purge valve
- A temporary blockage in the EVAP canister purge valve, purge pipe, or EVAP canister
- FTP sensor is out-of-calibration, damaged or "skewed"
- Purge solenoid valve is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).