

CADILLAC P1526: TP SENSOR LEARN NOT COMPLETED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes

What Does The Cadillac P1526 Code Mean?

Engine running and the PCM detected the TP Sensor Learn Value was not stored.

Note: Do not move the throttle during the TP Sensor Learn procedure or this code will reset.

What Are The Potential Causes Of The Cadillac P1526 Code?

- Throttle body valves or linkage is binding or sticking
- TP sensor is damaged or has failed (erratic TP sensor signals)

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).