

CADILLAC P1532: A/C EVAPORATIVE TEMP SENSOR CIRCUIT LOW INPUT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	Yes

What Does The Cadillac P1532 Code Mean?

Engine started; A/C switch and A/C Clutch "on", and the PCM detected the A/C Evaporator Temperature sensor indicated less than 2°F for 5 seconds during the test.

What Are The Potential Causes Of The Cadillac P1532 Code?

- A/C pressure switch circuit is shorted to ground
- A/C pressure switch VREF circuit is open or shorted to ground
- A/C pressure switch is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).