

CADILLAC P1536: ENGINE COOLANT OVER TEMPERATURE - AIR CONDITIONING (A/C) DISABLED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac P1536 Code Mean?

The DIM must be powered.

What Are The Potential Causes Of The Cadillac P1536 Code?

If DTC P1536 is stored as a history code it indicates that the DIM did receive a high engine coolant temperature message from the PCM. Interrupting A/C compressor operation can occur as a normal function to protect the engine from overheating.

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).