

CADILLAC P1539: AIR CONDITIONING CLUTCH STATUS HIGH INPUT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac P1539 Code Mean?

Engine started; A/C Clutch relay disengaged, and the PCM detected the A/C status (voltage) was high for 5 seconds.

What Are The Potential Causes Of The Cadillac P1539 Code?

- A/C clutch status circuit is shorted to system power (B+)
- A/C clutch relay is damaged or has failed (contacts are stuck)
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).