CADILLAC P1564: VEHICLE ACCELERATION TOO HIGH - CRUISE CONTROL DISABLED		
OVERVIEW		
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

## What Does The Cadillac P1564 Code Mean?

Engine started, engine running with Cruise Control requested and engaged, and the PCM detected an extremely rapid rate of vehicle acceleration during certain driving conditions.

## What Are The Potential Causes Of The Cadillac P1564 Code?

This code sets after a sudden rate of increase in vehicle speed occurs (i. e. , vehicle speed sensing problem or traveling on icy roads) while the cruise is engaged, so it is necessary to check with the customer to verify the conditions present when it set.

## **Reference Sources**

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

