

CADILLAC P1566: ENGINE SPEED TOO HIGH - CRUISE CONTROL DISABLED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac P1566 Code Mean?

Engine started; Cruise Control system requested and engaged, and the PCM detected the engine speed was more than 6300 rpm under these operating conditions.

How Can You Fix The Cadillac P1566 Code?

- Verify that there are not ABS/TCM trouble codes set
- Verify that there are no TCM related trouble codes set

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).