

CADILLAC P1579: P/N TO D/R AT HIGH THROTTLE ANGLE - POWER REDUCTION MODE ACTIVE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$80-\$150
Can I Still Drive?	:	Yes

What Does The Cadillac P1579 Code Mean?

Test Conditions DTCs [P0122](#) and [P0123](#) not set. Failure Conditions Gear selection from Park or Neutral to Drive or Reverse. Vehicle speed less than 6 MPH. Engine speed greater than 2000 RPM. Throttle angle of

What Are The Potential Causes Of The Cadillac P1579 Code?

If the drivers actions caused this DTC to set, clear the DTC and inform customer of proper shift procedure. Manipulate the wire harness while watching the scan tool display looking for opens and shorts. Reviewing the Failure Rec.

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).