

CADILLAC P1760: TCM SUPPLY VOLTAGE INTERRUPTED (4L30-E)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes

What Does The Cadillac P1760 Code Mean?

Key on or engine running; and the TCM detected a Keep Alive Memory circuit was interrupted. Circuits A828 and X837 are the power supply feeds for the TCM Keep Alive Memory. These fused circuits supply constant voltage on terminals 26 and 54 of the TCM.

What Are The Potential Causes Of The Cadillac P1760 Code?

- Perform the Powertrain Onboard Diagnostics System Check
- Refer to the repair information for DTC P0120
- TCM flashes the Sports Lamp when this code is set

Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.